

HISTORIC PRESERVATION REVIEW COMMISSION



TERRY BREJLA, CHAIR LISA DEHART, VICE CHAIR

SPECIAL MEETING HISTORIC PRESERVATION REVIEW COMMISSION CDD CONFERENCE ROOM, 4TH FLOOR 48 YANEY AVENUE, SONORA February 11, 2025

4:00 p.m.

You also may submit written comments by U.S. Mail to 2 South Green Street, Sonora, CA 95370 or email (cdd@tuolumnecounty.ca.gov) for retention as part of the administrative record. Comments will not be read during the meeting.

PUBLIC FORUM: 15 minutes

The public may speak on any item not on the printed agenda. No action may be taken by the Commission.

COMMISSION BUSINESS:

A. Reports from Commissioners and staff

PUBLIC HEARING:

None

NEW BUSINESS:

- Groveland Community Hall Front Porch Side Door and Façade discussion and staff direction.
- Mills Act discussion.

OLD BUSINESS:

None


COMMITTEE REPORTS:


- Demolition Review Committee Committee report; take action as necessary.
- 2. Grant Committee Committee report; take action as necessary

ADJOURNMENT

The Minutes, Staff Reports, and other documents for the items referenced in this Agenda are available for review at the Tuolumne County Community Development Department, 48 Yaney, Sonora, California, and online at https://www.tuolumnecounty.ca.gov/140/Historic-Preservation-Review-Commission. Any other materials related to the items referenced in this Agenda that are provided by the County to the HPRC Commissioners prior to the meeting are available for review at the Tuolumne County Community Development Department, 48 Yaney, Sonora, California, and will be available at the meeting. Any materials provided to the Commissioners during the meeting by the County will be available for review at








DEMO PLAN


NEW EXTERIOR ELEVATION




ENTRY OPTION 1

1/8" = 1'-0"






DEMO EXTERIOR ELEVATION





NEW EXTERIOR ELEVATION



TO MATCH EXISTING: ASPHALT SHINGLES O/


WEATHERPROOFING O/

2x WOOD FRAMING

PLYWOOD SHEATHING O/









WALL FRAMING SET ON SIDEWALK





EXTERIOR WALL SILL
PLATE IS SET ON
SIDEWALK, NOT BUILDING
SLAB







