

 INVOICE
 #74363

 SERVICE DATE
 Dec 12, 2023

 INVOICE DATE
 Dec 21, 2023

 DUE
 Upon receipt

 AMOUNT DUE
 \$787.50

Mill Villa Estates 18717 Mill Villa Rd Jamestown, CA 95327 CONTACT US

(209) 533-1010

watplumb51@yahoo.com

Service completed by: Robert Painter

(209) 288-9661

millvilla@ipgliving.com

INVOICE

Services

Irrigation leak in front of clubhouse

When we arrived on site and met with Adam we were shown an area where water has been coming out of the ground near some irrigation and the gate to the pool area. We started with shaving the grass so we could reinstall it when we're done with the repair. Just under the grass I found a couple of lines a 3/4" sprinkler line a 2" supply line and a couple of electrical lines. 1 of them had been cut by someone previously and another with No Conduit to protect the Rome that shouldn't even be in the ground. Because of the broken electrical and the exposed Romex I used my large shop vac to remove the mud and rocks to expose the leaky 2" SCH 40 PVC supply leaking from a glue coupler. When we looked for a valve to isolate the line we found a ball valve in front of the office we were able to close and stop the leak until we can make the repair.

Total

\$787.50

Thank you for letting Waters Plumbing Heating & Air be of service to you. License # 463958

INVOICE

Venture General Contracting Corp.

16759 Nandina Ave Riverside, CA 92504 venturegccorp@gmail.com (951) 476-9999

Mill Villa Estates

Bill to

Mill Villa Estates 18717 Mill Villa Rd Jamestown, CA 95327

Invoice details

Invoice no.: 1767 Terms: Due on receipt Invoice date: 11/13/2023 Due date: 11/13/2023

#	Date	Product or service	SKU	Qty	Rate	Amount
1.		Services		6	\$85.00	\$510.00
		Emergency leak repair - labor assistance. 3 men, 6 hours total				

Ways to pay

BANK

Note to customer

Thank you for giving us the opportunity to serve you. Please pay from this invoice.

Pay invoice

\$510.00

Total



BILL TO

Mill Villa Estates*
18717 Mill Villa Road
Jamestown, CA 95327 USA

INVOICE 23905

INVOICE DATE
Oct 31, 2024

JOB ADDRESS

Mill Villa Estates 18717 Mill Villa Road #340 Jamestown, CA 95327 USA Completed Date: 10/31/2024

Payment Term: Due Upon Receipt

Due Date: 10/31/2024

DESCRIPTION OF WORK

Arrived on site to find mainline, holding water. Pull toilet in back bathroom and ran senior machine down 50' and didn't hit a blockage. Pulled machine back and looked under house. Found section of pipe where glue seal was broken on 3" mainline and a belly had formed likely causing the backup. Pulled section of pipe with the broken glue seal and re-glued. Used P-Tape to level and strap section that had the belly. Ran water down kitchen sink, Toilet, and bathroom sink to make sure water was flowing. Water ran out of the pipe into the main indicating the water was no longer backing up. Noticed sink was leaking out of $1\frac{1}{2}$ line dropping into the main. Fixed using a Ferco and no more leaks occurred. No further issues at this time.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLR	Plumbing Labor Residential M-F REG: Plumbing Labor Residential Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	3.00	\$230.75	\$692.25
Gold Customer Discount	Gold Customer Discount: Gold Customer Discount 20% off labor	3.00	\$-46.15	\$-138.45

Materials

MATERIAL	DESCRIPTION	QUANTITY	YOUR PRICE	YOUR
F1056150	Fernco 1-1/2 in. Cast Iron and Plastic Flexible Coupling P/N F1056150	1.00	\$18.33	\$18.33

Invoice #23905 004976 of 2

SUB-TOTAL \$572.13

TAX \$1.33

TOTAL DUE \$573.46

BALANCE DUE \$573.46

Thank you for choosing Roto-Rooter Sonora

CREDIT CARD PAYMENT AUTHORIZATION

Please pay total due amount. Thank you.

Print Name below as it appears on credit card

Payment Type Credit Card # EXP CVC

Name on card Signature

Remit to:

Amount Due:

CUSTOMER AUTHORIZATION

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1.5% per month shall be applied for overdue amounts.

Sign here Date 10/31/2024

CUSTOMER ACKNOWLEDGEMENT

I have inspected all of the work done by Roto Rooter pursuant to the contract terms. I find that all work has been completed in a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature her signifies my full and final acceptance of all work performed.

Sign here Date 10/31/2024

Invoice #23905 On Page 727 of 2



BILL TO Mill Villa Estates* 18717 Mill Villa Road Jamestown, CA 95327 USA

> INVOICE 23760

INVOICE DATE Oct 08, 2024

JOB ADDRESS
Mill Villa Estates
18717 Mill Villa Road #unit 425
Jamestown, CA 95327 USA

Completed Date: 10/8/2024 Payment Term: Due Upon Receipt

Due Date: 10/8/2024

DESCRIPTION OF WORK

Arrived on site to find dirt already backfield by Jason, all that was left was the rock to back fill and smooth out. Back filled Rock, sprayed down with water to wash dirt into rocks. Sprayed off walkway, used rag to clean up dirt on fence and side of house. Picked up caution tape and bags left behind smoothed out rock. All is well at this time.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLC	Plumbing Labor Commercial M-F REG: Plumbing Labor Commercial Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	3.00	\$230.75	\$692.25
	•	SUB-TOTAL TAX		\$692.25 \$0.00
	1	TOTAL DUE		\$692.25
	BAL	ANCE DUE		\$692.25

Thank you for choosing Roto-Rooter Sonora



BILL TO
Mill Villa Estates*
18717 Mill Villa Road
Jamestown, CA 95327 USA

INVOICE 23715

INVOICE DATE Sep 27, 2024

JOB ADDRESS Mill Villa Estates 18717 Mill Villa Road Jamestown, CA 95327 USA

Completed Date: 9/27/2024

Customer PO: Space 438 Leak at Utility Box

Payment Term: Due Upon Receipt

Due Date: 9/27/2024

BALANCE DUE

DESCRIPTION OF WORK

Arrived on site. Water coming from communication box, water leaking from unit 425, dug approx 10ft by 4ft hole, observed leak, put on repair coupling.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLC	Plumbing Labor Commercial M-F REG: Plumbing Labor Commercial Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	12.00	\$230.75	\$2,769.00

Materials

Materials				
MATERIAL	DESCRIPTION	QUANTITY	YOUR PRICE	YOUR TOTAL
MISS3X4	MISSION 3X4 ARC 4BAND COUPLING PLXPL	1.00	\$34.50	\$34.50
		SUB-TOTAL TAX		\$2,803.50 \$2.50
		TOTAL DUE		\$2,806.00

Thank you for choosing Roto-Rooter Sonora

\$2,806.00



BILL TO
Mill Villa Estates*
18717 Mill Villa Road
Jamestown, CA 95327 USA

INVOICE 23730

Oct 01, 2024

JOB ADDRESS
Mill Villa Estates
18717 Mill Villa Road
Jamestown, CA 95327 USA

Completed Date: 10/1/2024 Payment Term: Due Upon Receipt

Due Date: 10/1/2024

DESCRIPTION OF WORK

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLC	Plumbing Labor Commercial M-F REG: Plumbing Labor Commercial Monday through Friday from 8:00 AM 5:00 PM \$ 230.75 per hour	4.00 to	\$230.75	\$923.00
PPC	Pro Press Commercial: Pro Press Equipment Charges Commercial	1.00	\$50.00	\$50.00
Materials				
MATERIAL	DESCRIPTION	UANTITY	YOUR PRICE	YOUR TOTAL
SBAG	QUICKRETE -ALL PURPOSE SAND	8.00	\$20.00	\$160.00
A10075808	3/4 In. Copper x Male Adapter P/N A10075808	1.00	\$16.96	\$16.96
/78177	ProPress® 3/4 in. Press Coupling (Less Stop) P/N V78177	1.00	\$18.83	\$18.83

1 /77004	

Viega ProPress® 3/4 in. Press Short Radius 90 Degree Elbow P/N V77022

1.00

\$10.73

\$10.73

typi 3/4 type L at a 20'

1.00

\$135.19

\$135.19

SUB-TOTAL

\$1,314.71

TAX

\$24.77

TOTAL DUE

\$1,339.48

BALANCE DUE

\$1,339.48

Thank you for choosing Roto-Rooter Sonora

CREDIT CARD PAYMENT AUTHORIZATION

Please pay total due amount. Thank you.

Print Name below as it appears on credit card

Credit Card #

EXP

CVC

Payment Type Name on card

Signature

Remit to:

Amount Due:

CUSTOMER AUTHORIZATION

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1.5% per month shall be applied for overdue amounts.

Sign here

Date 10/1/2024

CUSTOMER ACKNOWLEDGEMENT

I have inspected all of the work done by Roto Rooter pursuant to the contract terms. I find that all work has been completed in a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature her signifies my full and final acceptance of all work performed.

Sign here

Date 10/1/2024



BILL TO
Mill Villa Estates*
18717 Mill Villa Road
Jamestown, CA 95327 USA

INVOICE 23205

Jul 05, 2024

JOB ADDRESS Mill Villa Estates 18717 Mill Villa Road Jamestown, CA 95327 USA

Completed Date: 7/5/2024
Payment Term: Due Upon Receipt

Due Date: 7/5/2024

DESCRIPTION OF WORK

Use Leaf locator at unit 233 to try to find leak in driveway. Use locating device and was only able to pick up small signal few feet from meter boxes in Street. Will write estimate for exploratory digging on waterline.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
Leak Locator Residential	Leak Locator Residential: Leak Locator Residential \$ 288.75 per hour	1.00	\$288,75	\$288.75
		SUB-TOTAL TAX		\$288.75 \$0.00
		TOTAL DUE		\$288.75
Thank you for o	hoosing Roto-Rooter Sonora	BALANCE DUE		\$288.75
	AYMENT AUTHORIZATION I due amount. Thank you.			
Print Name belo	ow as it appears on credit card			
Payment Type Name on card Signature Remit to:	Credit Card #	EXP	CVC	

Amount Due:



BILL TO
Mili Vilia Estates*
18717 Mili Vilia Road
Jamestown, CA 95327 USA

INVOICE 23170 INVOICE DATE Jun 27, 2024

JOB ADDRESS
Mill Villa Estates
18717 Mill Villa Road
Jamestown, CA 95327 USA

Completed Date: 7/5/2024
Payment Term: Due Upon Receipt
Due Date: 6/27/2024

DESCRIPTION OF WORK

Arrived on site. Seen water seeping up through asphalt before bridge. Advised cistomer eigher cut up asphalt and replace or cut,cap and reroue. Customers says to reroute tompreow morning before trafgic hits. Apprx 60ft of 3/4 pvc will neex to be ran. Used leak locator and couldn't pinpoint leak. Did notice that tud marked asphalt for USA. Will wait for tud outcome.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLR	Plumbing Labor Residential M-F REG: Plumbing Labor Residential Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	1.00	\$230.75	\$230.75
Gold Customer Discount	Gold Customer Discount Gold Customer Discount 20% off labor	1.00	\$-46.15	\$-46.1 5

\$UB-TOTAL \$184.60

TAX \$0.00

TOTAL DUE \$184.60

BALANCE DUE \$184.60

Thank you for choosing Roto-Rooter Sonora



BILL TO
Mill Villa Estates*
18717 Mill Villa Road
Jamestown, CA 95327 USA

INVOICE 22761

Apr 24, 2024

JOB ADDRESS Mill Villa Estates 18717 Mill Villa Road Jamestown, CA 95327 USA

Completed Date: 4/24/2024 Payment Term: Due Upon Receipt

Due Date: 4/24/2024

DESCRIPTION OF WORK

Arrived on-site to perform estimate and found 3/4 inch PVC pipe leaking from a cracked 45. Customer asked me if I could do it for under \$500 and I said yes and they gave me approval to work. Cut out existing PVC4.5 and repaired using new 45 with 2PVC stubs on each side and connecting both sides with PVC couplings. Advise customer that due to the temperature outside it is better to wait at least a couple hours to turn water back on and they are in agreement. No further issues.

Please calculate 15% discount for park.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLC	Plumbing Labor Commercial M-F REG: Plumbing Labor Commercial Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	1.00	\$230.75	\$230.75

Materials

MATERIAL	DESCRIPTION	QUANTITY	YOUR PRICE	YOUR TOTAL
CP4F	3/4 in. Socket Straight DR 11 CTS CPVC 45 Degree Elbow P/N CP4F	1.00	\$3.82	\$3.82
CPCF	3/4 in. CTS x Socket Straight SDR 11 CPVC Coupling P/N CPCF	2.00	\$1.81	\$3.62

CPFGPF10

3/4 in. SDR 11 Flowguard Gold® CPVC Pressure Pipe P/N CPFGPF10

1.00

\$3.28

\$3.28

SUB-TOTAL

\$241.47

TAX

\$0.78

TOTAL DUE

\$242.25

BALANCE DUE

\$242.25

Thank you for choosing Roto-Rooter Sonora

CREDIT CARD PAYMENT AUTHORIZATION

Please pay total due amount. Thank you.

Print Name below as it appears on credit card

Payment Type

Credit Card #

EXP

CVC

Name on card

Signature

Remit to:

Amount Due:

CUSTOMER AUTHORIZATION

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1.5% per month shall be applied for overdue amounts.

Sign here

MM

Date 4/24/2024

CUSTOMER ACKNOWLEDGEMENT

I have inspected all of the work done by Roto Rooter pursuant to the contract terms. I find that all work has been completed in a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature her signifies my full and final acceptance of all work performed.

Sign here

Date 4/24/2024

INVOICE

Bill To

Mill Villa Estates Mobile Home Park 18717 Mill Villa Rd Jamestown, CA 95327 (209) 533-3151

Newkirk's Plumbing

Soulsbyville, CA 95372 Phone: (209) 770-0505

Email: newkirksplumbing@gmail.com

Payment terms Due upon receipt

Invoice #

1036

Date

05/21/2024

Description

Main Water Line Shut-Off Valve

Installed new 3/4" copper main water line shut-off ball valve.

Subtotal \$285.00 Total \$285.00

Notes:

Space #332

Per Maintenance, they did not want to shut off the entire street, so they had me stack the ball valve versus replacing it.

Thank you so much for your business!

INVOICE

Bill To

Mill Villa Estates Mobile Home Park 18717 Mill Villa Rd Jamestown, CA 95327 (209) 533-3151

Newkirk's Plumbing

Soulsbyville, CA 95372 Phone: (209) 770-0505

Email: newkirksplumbing@gmail.com

Payment terms Due upon receipt

Invoice #

1037

Date

05/23/2024

Description

Hose Bibb - Replacement

Replaced existing Hose Bibbs with new 3/4" Hose Bibbs

Subtotal

\$235.00

Total

\$235.00

Notes:

Space #332

Michael Newkirk

Mill Villa Estates Mobile Home Park



BILL TO
Mill VIlla Estates*
18717 Mill VIlla Road
Jamestown, CA 95327 USA

INVOICE 22921

May 23, 2024

JOB ADDRESS
Mill Villa Estates
18717 Mill Villa Road
Jamestown, CA 95327 USA

Completed Date: 5/23/2024 Customer PO: Space # 201 Payment Term: Due Upon Receipt

Due Date: 5/23/2024

DESCRIPTION OF WORK

I arrived on-site to find Clean out on the side of Space 201 overflowing. Ran senior Machine with 4 inch double blades through clean out but could not get more than one foot. I switched to a single blade and was finally able to get through trouble area. I then switch to a 3 inch double blade and worked my line back and forth through trouble area. Finally I switch to a 4 inch blade and also ran it back and forth through trouble area. I use camera to inspect the area and there is a substantial break in the line and very large amounts of roots in the line. I was able to clear the line enough to make the water flow but because of the brake my blades are hitting the plastic and it's not allowing me to cut the roots. My recommendation is To use the hydro jet to cut the roots enough to make the line flow properly. I will also talk to customer about doing a spot repair in that area on the broken pipe. No further issues

TASK	DESCRIPTION	QTY	PRICE	TOTAL
DCR	Drain Cleaning Residential M-F REG: Drain Cleaning Residential Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	2.25	\$230.75	\$519.19
Camera Commercial M- F REG	Camera Commercial M-F REG: Camera Commercial M-F REG \$ 288.75 per hour	1.00	\$288.75	\$288.75
Gold Customer Discount	Gold Customer Discount: Gold Customer Discount 20% off labor	1.00	\$-103.84	\$-103.84

SUB-TOTAL

\$704.10

TAX

\$0.00

TOTAL DUE

\$704.10

BALANCE DUE

\$704.10

Thank you for choosing Roto-Rooter Sonora

CREDIT CARD PAYMENT AUTHORIZATION

Please pay total due amount. Thank you.

Print Name below as it appears on credit card

Credit Card #

EXP

CVC

Payment Type Name on card

Signature

Remit to:

Amount Due:

CUSTOMER AUTHORIZATION

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1.5% per month shall be applied for overdue amounts.

Sign have

MM

Date 5/23/2024

CUSTOMER ACKNOWLEDGEMENT

I have inspected all of the work done by Roto Rooter pursuant to the contract terms. I find that all work has been completed in a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature her signifies my full and final acceptance of all work performed.

Sign here

MM

Date 5/23/2024

Invoice



Invoice number 675B31CF-0003
Date of issue June 3, 2024
Date due June 18, 2024

J Hart Plumbing Inc

Bill to

Mill VIIIa Estates 18717 Mill VIIIa Road Jamestown, CA 95327 United States

millvilla@ipgliving.com

\$1,592.02 USD due June 18, 2024

Pay online

Licenses: 459194.

Submit payment online or remit check to:

J. Hart Plumbing, inc.

18887 Plum Industrial Court

Sonora, CA 95370

(209) 533-1978

All past due involves are subject to lete for

All past due invoices are subject to late fees of 2.5% per month. Estimates may be withdrawn if not accepted within 45 days.

Description		Qty	Unit price	Amount
Labor: 5/16/24- Dug up and repaired water leak underground		1	\$1,360.00	\$1,360.00
Materials:		1	\$62.02	\$62.02
Labor: 5/23/24 - Backfill with sand and dirt.		1	\$170.00	\$170.00
	Subtotal			\$1,592.02
	Total			\$1,592.02
	Amount due			\$1,592.02 USD

Invoice



Invoice number 48A5712A-0001
Date of issue May 16, 2024
Date due May 31, 2024

J Hart Plumbing Inc

Bill to

Mill Villa Estates 18717 Mill Villa Road Jamestown, CA 95327 United States millvilla@ipgliving.com

\$440.00 USD due May 31, 2024

Pay online

Licenses: 459194.
Submit payment online or remit check to:
J. Hart Plumbing, Inc.
18887 Plum Industrial Court
Sonora, CA 95370
(209) 533-1978

All past due invoices are subject to late fees of 2.5% per month. Estimates may be withdrawn if not accepted within 45 days.

Description	Qty	Unit price	Amount
Service Call: Called out to locate a leak between space #120 & #121. Found water from French drain. Techs used camera and leak detector to trace leak to irrigation located at space #123. Additional testing showed that water flows down French d with tenant at #123 uses outside irrigation. Leak will need to be repaired by a landscaping company.	box	\$185.00	\$185.00
Additional Labor: Labor per hour after initial service charge. (1.5 hrs @ \$170/hr)	1	\$255.00	\$255.00
Subtotal			\$440.00
Total			\$440.00
Amount due			\$440.00 USD



BILL TO
Mili Vilia Estates*
18717 Mili Vilia Road
Jamestown, CA 95327 USA

INVOICE 22740

Apr 23, 2024

JOB ADDRESS Mili Vilia Estates 18717 Mili Vilia Road Jamestown, CA 95327 USA

Completed Date: 4/23/2024 Payment Term: Due Upon Receipt

Due Date: 4/23/2024

DESCRIPTION OF WORK

Roto-Rooter Wili arrive on-site and excavate located area where water is entering conduit pipe. Once pipe is exposed hopefully water line will be underneath it and leak will be found. If we can find it, it will be repaired but this estimate does not include materials because we do not know what is Going to be needed for repair. Estimate is for 1 day of labor Without materials. Concrete alongside of walkway might need to be removed for repair as well. Estimate will not include putting back concrete. If leak on water line is not located Then continuous work will be done to locate leak.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
RL	Repair Labor- Tech: Repair Tech \$ 230.75 PER HOUR PER MAN	8.00	\$230.75	\$1,846.00
2MPC	2nd Man Plumbing Commercial M-F REG: 2nd Man Plumbing Commercial Monday through Friday from 8:00 AM to 5:00 PM (per hour)	8.00	\$185.00	\$1,480.00

\$3,326.00 \$3,000 TOTAL DUE \$3,326.00

BALANCE DUE

\$3,326.00

Thank you for choosing Roto-Rooter Sonora



BILL TO Mill Villa Estates* 18717 Mill Villa Road Jamestown, CA 95327 USA

> INVOICE 22717

Apr 19, 2024

JOB ADDRESS
MIII VIIIa Estates
18717 Mill VIIIa Road
Jamestown, CA 95327 USA

Completed Date:

Payment Term: Due Upon Receipt

DESCRIPTION OF WORK

arrived on-site and used camera to chase leak through conduit running underground.. found water leaking on side oh home at space 425.

Dug and used camera to locate where water is entering conduit.

We believe leak is directly under conduit.

Will present estimate to customer for approval.

Total on today's work, and on estimate are pre 15% discount.

TASK	DESCRIPTION	QTY	PRICE	TOTAL
PLR	Plumbing Labor Residential M-F REG: Plumbing Labor Residential Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	3.00	\$230.75	\$692.25
2MPR	2nd Man Plumbing Residential M-F REG: 2nd Man Plumbing Residential Monday through Friday from 8:00 AM to 5:00 PM \$1855.00 per hour	2.00	\$185.00	\$370.00

SUB-TOTAL \$1,062.25 **TAX** \$0.00

TOTAL DUE \$1,062.25

BALANCE DUE

Thank you for choosing Roto-Rooter Sonora

Invoice #22717

Page 1 of 2 004259

\$1,062,25

CREDIT CARD PAYMENT AUTHORIZATION Please pay total due amount. Thank you. Print Name below as it appears on credit card **Payment Type** Credit Card # EXP CVC Name on card Signature Remit to: **Amount Due: CUSTOMER AUTHORIZATION** This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1.5% per month shall be applied for overdue amounts. Sign here Date **CUSTOMER ACKNOWLEDGEMENT** I have inspected all of the work done by Roto Rooter pursuant to the contract terms. I find that all work has been completed in a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature her signifies my full and final acceptance of all work performed.

Date

Sign here



BILL TO Mill Villa Estates* 18717 Mill Villa Road Jamestown, CA 95327 USA

INVOICE 22709

invoice date Apr 18, 2024

JOB ADDRESS
Mill Villa Estates
18717 Mill Villa Road
Jamestown, CA 95327 USA

Completed Date: 4/18/2024
Customer PO: leak by street - Melissa
Payment Term: Due Upon Receipt
Due Date: 4/18/2024

DESCRIPTION OF WORK

Arrived on-site to complaints of water leaking near street. Got approval to use leak locater.


Followed sounds near telecommunications box and dug under and found water coming out from 2in. Conduit, Box is locked, so we will pause job and wait for box to be opened to continue work.

No further issues

Office will deduct 15% off price

TASK	DESCRIPTION	QTY	PRICE	TOTAL
Leak Locator Residential	Leak Locator Residential: Leak Locator Residential \$ 288.75 per hour	1.00	\$288.75	\$288.75
PLR	Plumbing Labor Residential M-F REG: Plumbing Labor Residential Monday through Friday from 8:00 AM to 5:00 PM \$ 230.75 per hour	1.00	\$230.75	\$230.75
Gold Customer Discount	Gold Customer Discount: Gold Customer Discount 15% off labor	1.00	\$-77.93	\$-77.93

Invoice #22709 Page 1 of 2



SUB-TOTAL \$441.57 TAX \$0.00

BALANCE DUE

EXP

TOTAL DUE

\$441.57

\$441.57

Thank you for choosing Roto-Rooter Sonora

CREDIT CARD PAYMENT AUTHORIZATION

Please pay total due amount. Thank you.

Print Name below as it appears on credit card

Payment Type

Credit Card #

CVC

Name on card

Signature

Remit to:

Amount Due:

CUSTOMER AUTHORIZATION

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1.5% per month shall be applied for overdue amounts.


Date 4/18/2024

CUSTOMER ACKNOWLEDGEMENT

I have inspected all of the work done by Roto Rooter pursuant to the contract terms. I find that all work has been completed In a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature her signifies my full and final acceptance of all work performed.

Date 4/18/2024

Invoice #22709 Page 2 of 2





INVOICE #74363-2
SERVICE DATE Dec 28, 2023
INVOICE DATE Jan 23, 2024
DUE Upon receipt

AMOUNT DUE \$2,209.41

Mill Villa Estates 18717 Mill Villa Rd Jamestown, CA 95327 CONTACT US

(209) 533-1010

watplumb51@yahoo.com

Service completed by: Robert Painter, Roger Silva

(209) 288-9661 millvilla@lpgliving.com

INVOICE

Services

Repair irrigation leak at clubhouse

Repaired 2" PVC and 3/4" PVC. Backfilled and cleaned up job site.

Total \$2,209.41

Thank you for letting Waters Plumbing Heating & Air be of service to you. License # 463958





Po Box 144 Standard , CA 95373 209-984-9166

Bill To

Melissa

18717 mill villa rd

Jamestown, CA 95327

Date

Terms

10/9/2024

Due on receipt

PO Number

Account #

Property Address

Melissa

18717 mill villa rd

Jamestown, CA 95327

Date/Time	Description	Quantity	Price	Total
10/9/2024	Install 4 new 3/4" anti-siphon valves to lawn area near pool.	1.00	495.00	495.00

Subtotal:	495.00
Sales Tax	0.00
Invoice Total:	\$495.00

PAYMENT COUPON

Gibson Custom Landscape

Po Box 144

Standard, CA 95373

209-984-9166

Terms

Due on receipt

Account #

PO Number

Melissa

18717 mill villa rd

Jamestown, CA 95327

 Invoice #
 255

 Invoice Date
 10/9/2024

 Invoice Balance
 \$495.00

Amount Enclosed

004255





Po Box 144 Standard, CA 95373 209-984-9166

Bill To

Melissa

18717 mill villa rd Jamestown, CA 95327

Date Terms

10/9/2024

Due on receipt

PO Number Account #

Property Address

Melissa

18717 mill villa rd

Jamestown, CA 95327

72	Date/Time	Description	Quantity	Price	Total
	10/9/2024	locate and dig up main water line. Replace failing gate valve with new 3/4" ball valve to supply water to irrigation and spigot.	1.00	499.00	499.00

Subtotal:	499.00
Sales Tax	0.00
Invoice Total:	\$499.00

PAYMENT COUPON

Gibson Custom Landscape

Po Box 144 Standard, CA 95373 209-984-9166

Terms Account # Due on receipt

PO Number

Melissa

18717 mill villa rd Jamestown, CA 95327

256 Invoice # **invoice Date** 10/9/2024 **Invoice Balance** \$499.00

Amount Enclosed

004254



Invoice

ALL CREDIT CARD PAYMENTS WILL BE CHARGED A 3% FEE

Date	invoice #
10/16/2024	0112-3178

Bill To	Service at:	
Mill Villa Estates Chris Bowden	Mill VIIIa Estates 18717 Mill VIIIa Rd Jamestown, CA 95327 Club House	

Service Tag #	LARRY	Service Date	10/16/2024	-	Terms	Due on receipt
Description Service Call Labor - Service: TECH FOUND THE UNIT LOW ON REFRIGERANT, ALMOST EMPTY. TECH PUMPED THE UNIT UP WITH 300 PSI, OF NITROGEN TO LOOK FOR THE LEAK, TECH COULD NOT FIND THE LEAK IN THE SYSTEM. TECH RE-CHARGED THE UNIT FOR CUSTOMER TECH ALSO CHECKED THE HEATER WHERE HE FOUND A BAD INDUCER MOTOR. TECH EXPLAINED TO CUSTOMER THAT THIS NEEDS TO BE REPLACED, AND IT WILL BE AN ONGOING PROBLEM, WITH THE SYSTEM. BECAUSE OF THE LEAK BEING IMPOSSIBLE TO FIND, OUR TECH RECOMMENDS FOR CUSTOMER TO GET A NEW UNIT, DUE TO THE AGE OF THE SYSTEM BEING 30 PLUS YEARS OLD AND THE CONDITION OF THE SYSTEM. OUTDOOR COIL CLEANER			Description Qty Rate		Rate	Amount
			2	90.00 130.00	90.00 260.00	
efrigerant-8LBS OF R-42				8	15.00 125.00	15.00 1,000.00

Total	\$1,365.00
Payments/Credits	\$0.00
Balance Due	\$1,365.00



Invoice

ALL CREDIT CARD PAYMENTS WILL BE CHARGED A 3% FEE

Date	Invoice #			
8/27/2024	0112-2940			

Bill To	
Mill Villa Estates Chris Bowden	

Service at:

Mill Villa Estates
18717 Mill Villa Rd
Jamestown, CA 95327
Club House

Service Tag #	Service Date	7/31/2024		Terms	Due on receipt
Description Service Call - Local Labor - Service: FOUND UNITS ARE TWINED TOGETHER TOOK OUT BLOWER MOTORSAND SQUREILL CAGE NEED TO ORDER 2 1/3 3 SP MOTORS WITH CAPS WAS ABLE TO GET 1/2 OF THE BUILDING COOLING			Qty	Rate	Amount 90.00 130.00
			1	90.00 130.00	
abor - Service: NSTALLED 2 NEW 1/3 HP 3 SP MC EST RAN UNITS IOTH SYSTEM WERE OPERATION			2	130.00	260.00
quipment - 1/3 HP 3 SP MOTORS V	MTH CAPS		2	345.00	690.00

Payment is due at time of service.

Invoices not paid within 5 days will accure a \$75 service charge for every \$1,000.00 owed or 1.5% of total balance.

Total \$1,170.00

Payments/Credits \$0.00

Balance Due \$1,170.00



Invoice

ALL CREDIT CARD PAYMENTS WILL BE CHARGED A 3% FEE

Date	Invoice #
8/23/2024	0112-2913

Bill To	
Mill Villa Estates Chris Bowden	

Service at:

Mill Villa Estates
18717 Mill Villa Rd
Jamestown, CA 95327
LOT 511

Service Tag #	Service Date	8/23/2024		Terms	Due on receip	
Description			Qty	Rate	Amount	
NSPECTION OF FURNACE COUND LP SPRING FOR GAS VALCOUND LP ORIFICE FOR MAIN BUT SPECTED HEAT EXCHANGER COUND HEAT EXCHANGER IN GOTH CHECKED FOR SOOT OUND HEAT EXCHANGER CLEAT OUND DISCOLORATION ON BACURNACE HAS A CLEAN BILL OF HEAT EXCHANGER CLEAT OUND THE COUND HEAT EXCHANGER CLEAN BILL OF HEAT EXCHANGER BILL BILL BILL BILL BILL BILL BILL BIL	RNER # 45 OD WORKING ORDER N OF SOOT K OF HEAT EXCHANGE FROM MANU	FACTURING		150.00	150.0	

Total	\$150.00
Payments/Credits	\$0.00
Balance Due	\$150.00



Invoice

ALL CREDIT CARD PAYMENTS WILL BE CHARGED A 3% FEE

Date	Invoice#				
7/10/2024	0112-2636				

Bill To	Service at:	
Mill Villa Estates Chris Bowden	Mill Villa Estates 18717 Mill Villa Rd Jamestown, CA 95327 REC ROOM	

Service Tag #		Service Date	7/9/2024		Terms	Due on receipt
Description			Qty	Rate	Amount	
Service Call - Local Labor - Service: FOUND UNIT WITH BAD RUN CAP REPLACED WITH NEW TEST RAN UNIT SYSTEM WAS OPERATIONAL UPON JOB COMPLETION				90.00 130.00	90.00 130.00	
Equipment RUN CAP					98,00	98.00
					.	

Total	\$318.00
Payments/Credits	\$0.00
Balance Due	\$318.00



Invoice

ALL CREDIT CARD PAYMENTS WILL BE CHARGED A 3% FEE

Date	invoice #
7/3/2024	0112-2595

Bili To	Service at:	
Mill Villa Estates Chris Bowden	Mill Villa Estates 18717 Mill Villa Rd Jamestown, CA 95327 # 543	

erms	Terms		Service Date		Service Tag #
Rate	Qty		tion	Descrip	
90.00 130.00	Qty		tion	on 1 condensing unit	Service Call - Local .abor - Service: Found a blown breaker of Replaced Fuse Fest Ran Unit System was operational

Total	\$220.00
Payments/Credits	\$0.00
Balance Due	\$220.00

Central

Invoice/Work Order

5/9/2024

Web Site: centralheatingandalr.com

1163 Mill Villa Ct Sonora, CA 95370 Phone: (209) 532-7132

Service Information

MILL VILLA ESTATES 18717 MILL VILLA RD JAMESTON, CA 95327

Contact: MELISSA Phone: 209-533-3151

E-mail: millvilla@lpgllving.com

Job Name 28301WO **Billing Information**

IPG

18717 MILL VILLA RD JAMESTOWN, CA 95327

Job Type PO # AIR CONDITIONING		Involce # 25048050924	Scheduled 05/09/2024	Start 3:00 PM	End 4:30 PM
Item	Description		Quantity	Rate	Amount
Diagnostic-125.00	Diagnostic Charge Zone 1		1.0000	\$125.0000	\$125.00
Fuel Surcharge	Fuel Surcharge	•	1.0000	\$10.0000	\$10.00
L48-024-30	Install digital-Program	mmable Thermostat	1.0000	\$0.0000	\$160.98

Job Subtotal: \$295.98 Sales Tax - 8.75: \$7.52 Payment Total: \$0.00

Total: \$303,50

Filters/Pads 1	Quantity	Filters/Pads 2	Quantity	Filters/Pads 3	Quantity
Filters/Pads 4	Quantity	Fifters/Pade 5	Quantity	Number of Tuneups	Contract Amount

Job Notes and Instructions:

A/C NOT KICKING ON, HEATER IS WORKING - GO INTO OFFICE THEY WILL TAKE YOU TO A/C UNITS

Terms for additional services:

Service required on weekends is billed at time and a half. On-site visits are billed in ¼ hour increments with a ½ hour minimum. On-site travel charges, phone and e-mail time, are billed in 10th of an hour increments.

Payment is expected at time of service after receipt of invoice at Standard Rate.

Late payments are subject to 1.5% late fee per month calculated from the day of service.

Returned checks result in a \$35 returned check charge.

Signature:	x			
------------	---	--	--	--



Sign up today to process payments online or go paperiess and receive invoices electronically.

Visit http://hdsupplyfacilities.bilitrust.com Login Token: TPG BBM HWB

INVOICE

PO Box 509058 • San Diego, CA 92150-9058

Page 1 of 1

265.31

Credit/Account Information 800/798-8888, FAX 800/930-4930 Orders/Product Information 800/431-3000, FAX 800/859-8889 Please Pay From Invoice Terms: Net 30 Days

A minimum late charge of \$2.00 or 1.5% per month (18% per year)

is charged on past due involces.

Invoice Date Invoice Number 11/07/2024 9231482406

HD Supply Facilities Maintenance, Ltd. Federal ID 52-2418852 11/07/2024 9231482405

Customer Number Ordered By Authorized By Order Number Purchase Order Number

14824706 MELISSA MONTGOMERY W228364948 Light post 426/Maint Items

Ship To:

Investment Property Group/MHP Mill Villa MHC LLC 18008 Sky Park Cir, # 200 Irvine CA 92614-6406

MILL VILLA MHC LLC 18717 MILL VILLA RD, OFC JAMESTOWN CA 95327-9670

Stock Number	Description	Product Category	Ordered	Shipped	Unit Price	Unit	Extension
184308 146666	7.5in Wht Adv Ctrl Hardwound Towels 6/Cs 1.3W Prairie Buib Solar Light 3" Mnt	JANITORIAL LIGHTING FIXTURES	2	2 1	77.01 93.35	CA EA	154.02 93.35
nitorial 1	Summary (Excluding Misc, Charges & Freight)					Ship Date 11/06/2024	Sub Total 247.3/
hting Fbdures 1	00.12					Pkg Count 2	
						Weight 42.86 LB	Freight 0.00
					Au-	LVR1	TOTAL

Question? Call Nikki Oakes at 800798888867 ext:67459 or email Nikki.Oakes@hdsupply.com

SUPPLY	Invoice Number: 9231482406 Amount Due: 265.31 Date Due: 12/07/2024
For proper credit to your account, please do not staple check to remittance form.	Amount Paid:
Please return this portion with payment.	_
Thank you for your order.	If amount paid differs from amount due, please check and explain on back.
	Mail To:

14824706 Investment Property Group/MHP Mill Villa MHC LLC 18006 Sky Park Cir, # 200 Irvine CA 92614-6406

HD Supply Facilities Maintenance, Ltd. P.O. Box 509058 San Diego, CA 92150-9058 Invoice: 2024-01104

Sierra Electric

13000 Shotgun Creek Dr. Jamestown, CA 95327 (209) 591-7555

C10-1005083

Name: Mill Villa Estates

Location: 18717 Mill Villa Rd. Jamestown, CA 95327

Phone: (724)766-2223

Email: cbowden@ipgliving.com millvilla@ipgliving.com

Price: \$808.89

- 1. Temporarily wired-up unit 405 on 11/01/24 so customer would have power for the weekend.
 - o Material-\$40.00
 - o Labor-\$125.00
- 2. Installed new main breaker at unit 405 for permanent repair.
 - o Material- \$518.89
 - o Labor-\$125.00

Invoice: 2024-00918

Sierra Electric

13000 Shotgun Creek Dr. Jamestown, CA 95327 (209) 591-7555

C10-1005083

Name: Mill Villa Estates

Location: 18717 Mill Villa Rd. Jamestown, CA 95327

Phone: (724)766-2223

Email: cbowden@ipgliving.com millvilla@ipgliving.com

Price: \$1,755.00

1. Installed 13 customer provided photocells.

Labor- \$975

2. Purchased and installed 1 photocell for pole light.

Labor- \$75

Material-\$35

3. Fixed wiring issue at unit 542.

Labor- \$250

4. Installed GFCI receptacle for sprinkler timer and fixed sagging coach light at unit 505.

Labor- \$375

Material- \$45

· SUPPLY

Sign up today to process payments online or go paperiess and receive invoices electronically.

Visit http://hdsupplyfacilities.bilitrust.com Login Token: TPG BBM HWB

PO Box 509058 • San Diego, CA 92150-9058

Page 1 of 1

Credit/Account Information 800/798-8888, FAX 800/930-4930 Orders/Product Information 800/431-3000, FAX 800/859-8889 Please Pay From Invoice Terms: Net 30 Days

A minimum late charge of \$2.00 or 1.5% per month (18% per year)

INVOICE

is charged on past due involces.

Invoice Date **Invoice Number** 09/15/2024

HD Supply Facilities Maintenance, Ltd. Federal ID 52-2418852 9229795805 **Customer Number** Ordered By Authorized By Order Number Purchase Order Number 14824706 **MELISSA MONTGOMERY** W227371606 maintenance/property items

Ship To:

Investment Property Group/MHP MIII VIIIa MHC LLC 18006 Sky Park Cir. # 200 Irvine CA 92614-6406

MILL VILLA MHC LLC 18717 MILL VILLA RD, OFC **JAMESTOWN CA 95327-9670**

Stock Number	Description	Product Category	Ordered	Shipped	Unit Price	Unit	Evtere	alon
117388 116126 145184 703638	117368 Printed Ktchn Papr Twl 24/Cs 116126 Fido Baggles Header Pet Wste Bags 12/Cs 145184 Wave 3d Urinal Screen Cttn Bissm 10/Pkg		1 1 1 1 10	1 1 1 1 10	107.72 147.19 25.29 10.85	CA PK	Extens	107.7 147.1 25.2 108.5
ounde 1	Summary (Excluding Misc. Charges & Freight) 57.86 42.65					Ship Date 08/30/2024	Sub Total	388.7
hting Fixtures 1'	16.37					Pkg Count 4	Sales Tax	28.1
					ħ	Weight	Freight	2011
						34.17 LB		0.0
					C	LVR1	TOTAL	
astion? Call Nikki	Oakes at 8007988888867 ext:67459 or email Nikki.Oakes	(Chdoumh) and				19		416.8

SUPPLY	

For proper credit to your account, please do not staple check to remittance form.

Please return this portion with payment.

Thank you for your order.

14824708 Investment Property Group/MHP Mili Villa MHC LLC 18006 Sky Park Cir, # 200 Irvine CA 92614-6406

Invoice Number:	9229795805
Amount Due:	416.88
Date Due:	10/15/2024

If amount paid differs from amount due,
please check and explain on back.

Mall To:

HD Supply Facilities Maintenance, Ltd. P.O. Box 509058 San Diego, CA 92150-9058

Invoice#2024-00201

Sierra Electric

13000 Shotgun Creek Dr. Jamestown, CA 95327 (209) 591-7555 C10-1005083

Name: Mill Villa Estates

Location: 18717 Mill Villa Rd. Jamestown, CA 95327

Phone: (724)766-2223

Email: cbowden@ipgliving.com millvilla@ipgliving.com

Price: \$1,280.00

- 1. Diagnosed electrical issue with unit #205. Found out the main breaker at the transformer was broken. 2hrs. X \$125-\$250
- 2. Replaced main breaker at transformer. 2hrs. X \$125- \$\$250 Material- \$550
- 3. Replaced dryer breaker at unit #239. (Managers Home) 1hr. X \$125- \$125 Material- \$105

Invoice#2023-01117

Sierra Electric

13000 Shotgun Creek Dr. Jamestown, CA 95327 (209) 591-7555 C10-1005083

Name: Mill Villa Estates (Jaime)

Location: 18717 Mill Villa Rd. Jamestown, CA 95327

Phone: (724)766-2223

Email: <u>cbowden@ipgliving.com</u> <u>millvilla@ipgliving.com</u>

Price: \$2,500.00

1. Repaired pedestal at unit #340





LOVE'S HONE CENTERS, LLC 120 OLD WARDS FERRY ROAD SONORA, CA 95370 (209) 596-6400

- SALE -SALESM: \$22790W1 1535935 TRANSH: 426092817 01-16-24

> 31567 ETN 158 120/2770 CMB0 SP/ 16.28 70590 ETN 158 120/277 COMB0 2 [11.28

> > SUBTOTAL: 27.56 TOTAL TAX: 2.41 IMMOTEE 81957 TOTAL: 29.97 DEBLIFUSA: 29.97

31TUISA: 29.97 CHANGE: 0.00

DERITUISA: XXXXXXXXXXXX7512 ANGUNT: 29.97 AUTHOD: 4:3914 SUIPED REFID:227909957698 01/16/24 14:03:29 TRACE: 957698 RETRIEVAL: 227909957698 PUBCHRSE RACK TUTAL DEBIT 29.97 0.00 29.97

STORE: 2279 TERRINAL: 89 01/16/24 14:03:35
NO OF ITEMS PURCHASED:
EXCLUDES FEES, SERVICES AND SPECTAL GROEF ITEMS

THANK YOU FOR SHOPPING LOWE'S.
FOR DETAILS ON OUR RETURN POLICY, VISIT
LOWES, LOW/RETURNS
A WRITTEN COPY OF THE RETURN POLICY IS AVAILABLE
AT OUR CUSTOMER SERVICE DESK

LOWEST PRICE WOMANNIER
FOR MORE DETAILS, VISIT LOWES.COM/LOWESTPRICESUANS (TEE

SHARE YOUR FEEDBACK!
ENTER FOR A CHANCE TO BE
ONE OF FINE \$500 WINNERS DRAWN HONTHLY!
1ENTRE EN EL SORTEO NEKSONL
PARA SEX UND DE LOS CINCO GANADORES DE \$500!

* NO PURCHASE RECESSARY TO ENTER OR WIN. *
* WOLD WHERE PROMIDITED. NUST BE IS OR OLDER TO ENTER. *
* OFFICIAL ROLES & WINNERS AT: www.lgups.com/sort.by *

STORE: 2279 TERRIURAL: 9 01/16/24 14:05:3