Invoice#2024-00312

Sierra Electric

13000 Shotgun Creek Dr. Jamestown, CA 95327 (209) 591-7555 C10-1005083

Name: Mill Villa Estates

Location: 18717 Mill Villa Rd. Jamestown, CA 95327

Phone: (724)766-2223

Email: <u>cbowden@ipgliving.com</u> <u>millvilla@ipgliving.com</u>

Price: \$448.53

1. Repaired pool pump conduit switch and wiring.

Joe Wheeler- 3hrs X \$125- \$375.00

Material- \$73.53

Creative Pool Designs

Invoice

RH 70:

Milia Wila Estatos Sonore, Çe




Date	Your Order#	Our Order#	Sales Rop.	FOR	Ship Via	Terms	
03/16/202	MV93	MV93	RC513			Upon Receipt	

Quantity	item	Bosoription	Unit Price	Total
		Rock added behind spa		\$400.00
		Removal of rock and tile installation		\$400.00
		Programming for new panel box		\$400.00
				+

Subtotal	\$1,200.00
Sales Tax Supplies	
Payment Received	
Balance Due	\$1,200.00

537 Pirmen Lane Modeste, Ca. 95345 209-322-5726



Mill Villa Assistant Manager

From: Mill Villa

Sent: Tuesday, April 16, 2024 2:31 PM **To:** Mill Villa Assistant Manager

Subject: FW: Mill Villa/ Pool Pump Repair **Attachments:** MV_Pool_Pump Bid 3.18.2024.pdf

Kind regards,



Melissa Montgomery
Mill Villa Estates Park Office
O: 209-533-3151 | millvilleingliving.com

From: Christopher Bowden <cbowden@ipgliving.com>

Sent: Monday, March 18, 2024 11:11 AM To: Mill Villa <millvilla@ipgliving.com>

Cc: Valerie Avila <vavila@ipgliving.com>; Laura Rivera <lrivera@ipgliving.com>

Subject: FW: Mill Villa/ Pool Pump Repair

Please proceed



Chris Bowden
Director of Construction and Maintenance
O: (949) 486-7153| |pgllving.com

From: Valerie Avila vavila@ioeliving.com>
Sent: Monday, March 18, 2024 11:06 AM

To: Christopher Bowden < cbowden@ipgliving.com >

Cc: Laura Rivera < raintera@ipgliving.com >; Mill VIIIa < millvilla@ipgliving.com >

Subject: Mill Villa/ Pool Pump Repair

Hi Chris,

Just our luck the pool pump requires replacement at Mill Villa. Total cost is: \$3,250. Let me know if you have any questions or if we are approved to move forward with this estimate. Thank you!



Valerie Avila
Regional Manager
D: 949-486-7175 [O: 949-440-2300 | vavila@lpgliving.com

From: Mill Villa <millvilla@ipgliving.com>
Sent: Monday, March 18, 2024 10:48 AM
To: Valerie Avila <vavila@ipgliving.com>

Subject: MV Pool Pump

Hi Valerie,

An update on the pool pump, the electrical wires were burnt, Sierre Electric came out last week and repaired the wires in the box as well as the wires behind the wall that were in need of repair. The pool wires are good, due to the pool pump motor going out, the pump needs to be replaced, this pump is no longer made, and parts are not available. The entire component (pump) needs to be replaced with a new pump.

Please see attached estimate for approval.

Kind regards,



Melissa Montgomery
MIII VIIIa Estates Park Office
O: 209-533-3151 | miliviliaipgliving.com

Carefree Pool Service Inc

PO Box 1382 Jamestown, CA 95327

Invoice

Date	Invoice #
4/29/2024	7033

Bill To	
Mill Villa 18006 Sky park Circle #200	
Irvine, Ca 92614	

Ship To		
Mill Villa 18006 Sky park Circle #200 Irvine, Ca 92614		
	t	

P.O. Number	Terms	Rep	Ship	Vla	F.O.B.		Project
	Due on rec	eipt	4/29/2024				
Quantity	Item Code	T '-	Descripti	on	Price I	Each	Amount
3	Labor	Labor Sales Tax Outsi	de City of Sonora			125.00 7.25%	375.00 0.00
		11-			Total		\$375.00

Carefree Pool Service Inc

PO Box 1382 Jamestown, CA 95327

Invoice

Date	Invoice #
5/1/2024	7269

Ship To

Mill Villa
18006 Sky park Circle #200
Irvine, Ca 92614

P.O. Number	Terms	Rep	Ship	Via	F.O.B.		Project	
	Due on receip	ot	5/1/2024					
Quantity	Item Code		Descript	on	Price E	ach	Amount	
1 1 1 1 1 1 1 1 1 1	Labor Subpanel 125AMP 20amp GFI Breaker 20Amp single GFCI Misc electrical Pentair Thermister Pentair Manifold B	Subpanel 125A 20amp GFI Bre 20Amp single C Misc Electrical Pentair Thermal Pentair Thermal Pentair Manifol	aker GFCI tter Regulator Kit			125.00 95.76 227.47 33.68 300.00 101.79 149.29 121.61 7.25%	1,250.00 95.76T 227.47T 33.68T 300.00T 101.79T 149.29T 121.61T 74.65	
					Total		\$2,354.25	

SIGNED BY:	liability to the customer scustomer for any inciden charges by the hour to lo leaks unless such guarant	recove workmanship only shall be limited to the ame tal or consequential dame ok for leaks. Company ma	i. In the event that Dunt of money pak Iges caused by con Ikes no cuarantees	company is unsucces I to company. In no e npanies fallure toproj thatits efforts will be	perly repair a leak. This co	npanies de cuba de v	 Prools, Spas & Fountains Water, Sewer or Gas Pipes Pool & Spa Crack Repair Leaks Under Concrete or Dirt Video Inspection of Pipes 	EHE ⊗
Commende to My milly mil	N.B. NO OTHER LEAKS WERE APPARENT AS AT TIME OF TEST WORK ORDERED BY: THE OWNER OR TENANT HAS THE RIGHT TO REQUIRE THE CONTRACTOR TO HAVE A PERFORMANCE CHARGES AS AGREED AND AGREE TO PAY THE TOTAL AMOUNT DUE ON PRESENTATION OF THIS INV TO PAY REASONABLE CHARGES FOR COLLECTION, INCLUDING ATTORNEY FEES, IN THE EVENT OF M	No leave defected in	We found that	Drain Stine Ja	JOBTYPE SPU LEAN DOLE	Repair Repair Repair Contact Rolando Argueta 877-232-6747 Cell: 510-815-5120 Fax: 510-236-5182	untains Gas Pipes C Repair C Repa	& B LEAK FINDERS
1 21	3 2 2 2 1 1 1 1	the plumbing	ts was clagged u	etsline 2 section + "	Sillow w/ Blue Pacu	OTH CITY CS.	0 E	Job Workorder / Invoice
14	TOTAL:\$ // OOD PAYMENT BOND, I FIND THE WORK SATISFACTORY AND THE OICE WITHOUT ANY DEDUCTION WHATSOEVER, I FURTHER AGREE Y DEFAULT, AS WELL AS PENALTY INTEREST AS ALL OWNERS.		and we	K Defected	Dects in the contract of the c	WORK DONE ON CONTRACT BASIS	OVE S - 8 - 202 U	Nº 15180